Deborah L Montgomery 11525 Moreno Ave. Lakeside, CA 92040 September 14, 2015

Mr. Hingtgen Department of Planning and Development Services 5510 Overland Avenue, Suite 310 San Diego, CA 92123

Re: PDS2015-RP-15-001, LOG NO. PDS2015-ER-98-14-016B

Dear Mr. Hingtgen:

Thank you for the opportunity to comment on the scope of the EIR for the above referenced project. I live near, and have hiked and ridden in, El Monte Valley many times and am aware that this project may have many environmental impacts, not only to the valley itself, but to the surrounding community.

During the preparation of the EIR, please make sure to fully address possible impacts on all aspects of:

- Handling of hazardous waste remaining in the soil from building the dam many years ago.
- Bridge weight limits, weight and vibration damage from heavily loaded trucks crossing the bridges in Lakeside.
- Hours of operation, noise impact to surrounding community.
- Lighting impact to the surrounding community.
- Spilling/leaking of sand on the roads causing accidents.
- Impact on traffic and timing getting through lights.
- Ground vibration impacts due to the mining, washing, and processing of aggregate.
- Greenhouse gases associated with aggregate mining and cement manufacture.
- Dust impact from disturbing a site known to have Valley Fever.
- Impacts to local wildlife such as bats, raptors, owls, fox, raccoons, wild cats, insects, frogs, etc.
- Irreversible damage to the aquifer.
- Contamination and impact of evaporation of the aquifer caused by opening it to the elements.
- Impact to wells and all dependent on the aquifer, including wildlife.

- West Nile increase due to more open water.
- Road damage and repair.
- Visual changes from a beautiful landscape to torn up dirt, trucks, cranes, and dust.
- Damage to established eco system and endangered animals within the valley.

Sincerely,

Deborah L Montgomery

Secretary, Lakeside Community Planning Group Secretary, Lakeside Frontier Riders Concerned Resident of Moreno Valley, Lakeside 619-857-0958 dlmx2@cox.net